

# Water Resources Department Records Guide

## Record Series Descriptions

### Photographs and Negatives (92A-006)

Photo title: Big Cliff Dam

Photo date: 1954

Amount: 1 photograph

Physical description: black and white photoprint

Dimensions: 3.5 x 4.5"

Location: Photograph Box 1 / Folder 51

Description: View of dam.

Photo title: Calapooya River

Photo date: 1961

Amount: 7 photographs

Physical description: black and white photoprint

Dimensions: 3 x 4.5" (1-6); 8 x 10" (7).

Location: Photograph Box 1 / Folder 22

Description: Views of flood damage to river banks along Calapooya River, Brownsville area, Linn County (1-6);  
View of bridge over Calapooya River at Holley (7).

Photo title: Cottage Grove Lake and Dam

Photo date: 1948-1955

Amount: 8 photographs and 1 negative

Physical description: black and white photoprints (1-8); negative (9)

Dimensions: 8 x 10" (1-7); 4.5 x 6.5" (8-9)

Location: Photograph Box 1 / Folder 23

Description: Views of Cottage Grove spillway, dam, and reservoir; views of boat races, sailboats, and recreational uses of lake.

Photo title: Dam Construction

Photo date: undated

Amount: 36 photographs; 27 negatives

Physical description: black and white photoprints of 1-36; negatives, 1-27

Dimensions: 5 x 7" (1-27, photoprints and negatives); 8 x 10" (28-36, photoprints)

Location: Photograph Box 1 / Folders 24-27

Description: Views of earth moving and other heavy equipment in process of construction a dam. Dam is not identified.

Photo title: Detroit Dam (Santiam River)

Photo date: 1949-1957

Amount: 63 photographs and reproductions of drawings

Physical description: black and white photoprints (61), copies of drawings (2)

Dimensions: size varies from 3.5 x 4.5 to 8 x 10"

Location: Photograph Box 1 / Folders 28-30

Description: Views of construction of Detroit Dam on the Santiam River including dam, lake, powerhouse, and Marion Forks Salmon Hatchery.

Photo title: Dorena Dam (Row River)

Photo date: 1946-1955

Amount: 24 photographs, 1 reproduction of drawing

Physical description: black and white photoprints, copy of drawing

Dimensions: size varies from 3 x 3 to 8 x 10"

Location: Photograph Box 1 / Folder 31

Description: Views of construction of Dorena Dam on the Row River including dam, river, lake, and people fishing.

Photo title: Fern Ridge Dam

Photo date: 1949-1955

Amount: 13 photographs

Physical description: black and white photoprints

Dimensions: size varies from 3 x 4 to 8 x 10"

Location: Photograph Box 1 / Folder 32

Description: Views of Fern Ridge Dam including lake, boats, and recreational activities.

Photo title: Flood

Photo date: 1941

Amount: 1 photograph, 1 negative

Physical description: black and white photoprint with negative

Dimensions: 4.5 x 6.5"

Location: Photograph Box 1 / Folder 33

Description: View of flooded river, unidentified.

Photo title: Gate Creek (McKenzie River)

Photo date: undated

Amount: 1 photograph

Physical description: black and white photoprint

Dimensions: 9.25 x 7.5"

Location: Photograph Box 1 / Folder 33

Description: View of Gate Creek, McKenzie River basin.

Photo title: Half Moon Bend  
Photo date: undated  
Amount: 2 photographs  
Physical description: black and white photoprints  
Dimensions: 6.75 x 10"  
Location: Photograph Box 1 / Folder 33  
Description: Views of bank of Half Moon Bend before and after improvements.

Photo title: Irrigation  
Photo date: undated  
Amount: 12 photographs  
Physical description: black and white photoprints  
Dimensions: size varies from 3.25 x 4.5 to 8 x 10"  
Location: Photograph Box 1 / Folder 34  
Description: Views of irrigation pumps, sprinklers, and irrigated crops.

Photo title: Jordan River Bridge  
Photo date: undated  
Amount: 1 photograph  
Physical description: black and white photoprint  
Dimensions: 8 x 10"  
Location: Photograph Box 1 / Folder 35  
Description: View of covered bridge over Jordan River.

Photo title: Leaburg Fish Hatchery  
Photo date: undated

Amount: 1 photograph

Physical description: black and white photoprint

Dimensions: 8 x 10"

Location: Photograph Box 1 / Folder 35

Description: View of river and fish hatchery.

Photo title: Linn County Flood

Photo date: 1960-1961

Amount: 68 photographs

Physical description: black and white photoprints

Dimensions: 8 x 10"

Location: Photograph Box 1 / Folders 36-39

Description: Views and aerial views of damage to river bank and farm fields caused by floods on Calapooya River, Thomas Creek, and South Santiam River.

Photo title: Lookout Point Dam and Reservoir, Meridian Site

Photo date: 1949-1955

Amount: 48 photographs

Physical description: black and white photoprints (46), drawings (2)

Dimensions: size varies from 3.5 x 4.5 to 8 x 10"

Location: Photograph Box 1 / Folders 40-42

Description: Views of dam, construction of dam and reservoir, relocation of railroad, generator and powerhouse, and dedication of dam on the Middle Fork Willamette River. Also Oak Ridge Salmon Hatchery.

Photo title: Marion Forks Salmon Hatchery

Photo date: undated

Amount: 1 photograph

Physical description: black and white photoprint

Dimensions: 8 x 10"

Location: Photograph Box 1 / Folders 43

Description: Aerial view of fish hatchery.

Photo title: Miscellaneous

Photo date: undated

Amount: 15 photographs

Physical description: black and white photoprints

Dimensions: Size varies from 4.5 x 6.5 to 8 x 10"

Location: Photograph Box 1 / Folders 53

Description: Views of erosion, river bank improvements, dam construction, and flood damage. Locations unidentified.

Photo title: Murphy Bar

Photo date: undated

Amount: 1 photograph

Physical description: black and white photoprint

Dimensions: 8 x 10"

Location: Photograph Box 1 / Folders 43

Description: View of river bank and improvements.

Photo title: Salt Creek

Photo date: undated

Amount: 2 photographs

Physical description: black and white photoprints

Dimensions: 8 x 10"

Location: Photograph Box 1 / Folders 44

Description: View of machinery digging ditch.

Photo title: South Santiam River

Photo date: undated

Amount: 3 photographs

Physical description: black and white photoprints

Dimensions: 8 x 10"

Location: Photograph Box 1 / Folders 44

Description: Views of flooding and flood damage to river bank and strawberry field along the South Santiam River three miles northwest of Jefferson.

Photo title: Tualatin River

Photo date: 1952-1953

Amount: 11 photographs

Physical description: black and white photoprints

Dimensions: 4.5 x 6.5"

Location: Photograph Box 1 / Folders 45

Description: Views of flooding and flood damage on the Tualatin River and its tributaries.

Photo title: Waterloo

Photo date: undated

Amount: 1 photograph

Physical description: black and white photoprint

Dimensions: 8 x 10"

Location: Photograph Box 1 / Folders 45

Description: View of river and falls.

Photo title: Willamette River

Photo date: 1932-1951

Amount: 29 photographs

Physical description: black and white photoprints

Dimensions: size varies from 2.5 x 4.5 to 8 x 10"

Location: Photograph Box 1 / Folders 49-50

Description: Views and aerial views of river and river bank improvements. Views of logging, log dumps, and log rafts; dredges and dredging operations; erosion and revetments.

Photo title: Willamette River Basin

Photo date: 1956-1959

Amount: 21 photographs

Physical description: black and white photoprints

Dimensions: size varies from 9 x 8 to 9 x 9"

Location: Photograph Box 1 / Folder 51

Description: Aerial views of rivers and surrounding farm land showing location of proposed projects to improve river banks and control erosion. McKenzie, Molalla, South Santiam, and Willamette Rivers.

Photo title: Willamette Valley Flood

Photo date: 1890-1945

Amount: 46 photographs

Physical description: black and white photoprints

Dimensions: size varies from 3 x 3 to 8 x 10"

Location: Photograph Box 1 / Folders 46-48

Description: Views and aerial views of flooding and flood damage. Views of buildings and farms under water and damage to river banks and



fields. Oregon City and Salem, 1890; Albany, Eugene,  
Springfield.

Photo title: Yamhill River

Photo date: 1951

Amount: 7 photographs

Physical description: black and white photoprints

Dimensions: 3.5 x 3.5"

Location: Photograph Box 1 / Folder 52

Description: Views of erosion, dredges, and log rafts.